

Safety Mechanism on Model 700 LH

Discussion Thread

Response (Chris)

5/25/2004 9:18:29 AM

Dear Paul,

Thank you for contacting Remington Country. According to the serial number, your Model 700 was produced in 1994. Your firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

[http://www.remington.com/safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/safety_Modification_Program/remington_safety.htm)

Customer (Paul Gilbert)

5/24/2004 5:00:14 PM

I have a friend that has a 700 (.270) that fired when the safety was clicked off. I just bought the .270 (used gun), and want to be sure that this issue isn't under a call back or warranty claim. The serial number is D6807050.

Please let me know if I have any need for concern.

Thanks, Paul