Possible accidental firing

Discussion Thread

Response (Chris) Dear Mr. Bradley, 11/10/2004 4:20:41 PM

Thank you for contacting Remington Country. Your Model 700 was produced in 1974. Your firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Thomas Bradley)

I own a 700 BDL in 300 Winchester Magnum. I am left handed and as this is a right handed rifle, I eventually purchased other rifles with which to hunt. I recently read about some of these gaps firing when they weren't supposed to. I have owned the rifle a long time but have rarely used it. The serial number is 6766201. Please advise if I should do anything. I was thinking of giving the rifle to my som in-law..thank you

