

remington 721 safety recall program

Discussion Thread

Response (Kati)  
Dear Steve:

12/21/2005 12:51:51 PM

Thank you for visiting Remington Country!

Safety Modification Program

Remington Model 721 & 722

If you own a Remington Model 721 or 722 rifle:  
All Remington Model 721 and 722 rifles were manufactured with a bolt-lock mechanism. These models were discontinued in 1961. If you participate in the Safety Modification Program, your firearm will be cleaned and inspected for proper functioning, by a qualified gunsmith. Once the condition of your firearm has been assessed, you will be notified of one of the following:

- Your rifle's trigger assembly is otherwise in good operating condition and the gunsmith will proceed to physically remove the bolt-lock feature so that your rifle can be loaded and unloaded while the safety remains in the "S" or "On Safe" position; or
- Your rifle's trigger assembly is found to be in an unsatisfactory or potentially unsafe operating condition because of any number of factors, including wear, alteration or maintenance. The entire trigger assembly will be replaced with a new factory trigger assembly, which does not incorporate a bolt-lock mechanism.

In either case, the total cost to you is \$20, plus tax. You will also receive a rebate coupon good for up to \$20 toward the purchase of any Remington safety product, including gun locks, hearing and eye protection, and gun safes.

How to participate in the Safety Modification Program

Complete the General Repair Form and send or deliver your firearm and the completed repair form to either:

- a) A Remington Authorized Repair Center; or
- b) Ship your firearm to the Remington factory at:  
Remington Arms Company, Inc.  
Ilion Firearms Plant  
Attention: BL Safety Program  
14 Hoefer Avenue  
Ilion, NY 13357

Remington will bill or arrange for payment once your firearm is received and evaluated.

**CAUTION:** It is your responsibility to comply with all laws and regulations regarding transportation or shipping of your firearm. Absolutely no ammunition should be packaged with the firearm whether loaded in the firearm itself or included in the shipping container. The firearm should be transported only in a completely unloaded condition.

You may contact us at 1-800-243-9700 M-F 9-5pm EST. if additional information is needed. You may access and print the General Repair form by accessing our Support option, typing in the Topic of all and Keyword search of Repair Form: #2 How do I send my Remington firearm to the

factory for repair; at the bottom of the page it will say: For a factory repair form, go Here. You can print from this screen.

K. Howerton  
Consumer Services

Customer (Steve Davis) 12/15/2005 2:45:23 PM  
What form is needed to send the firearm for modification? Is it available online?