

Rear spacer of SPL
MIM LH Side Plate
removed and
replaced with
separate spacer
block in Trigger
Housing

