REMINGTON ARMS COMPANY, INC. Product Team Meeting Agenda

November 17th, 2004 7:30 am EST - Ilion

Future Meetings

December 15th- Ilion

Future Important Dates

January 28th – 31st SHOT Show – Las Vegas, NV April 15th -17th NRA Show – Houston, TX

Business Review

Jay Bunting to provide overview of current business environment

ILION BASED SHOTGUN PRODUCTS

New Shotgun Product

Model 332-Skinner, Orf.

OBJECTIVE: Establish a legitimate presence in the ON market Production Status:

Shooting Open-Update

Top Lever Template

Grinding Lugs

Communicating with Arms Service-Any New Repairs?

Action: Look at improving efficiencies and cost. (Orf)

Potential Show Special-M332 Camo-Need to have (2) 26" bbl guns & (2) 28" bbl guns dipped in New Mossy Oak Break-Up and (1) 30" bbl gun in New Shadowgrass by Mid-December 2004.

M332 Sporting DL-D.Diaz

Need 10K rounds shot through 3 guns to assess durability of design. Need to look at frame treatment. R. Murphy to work with B. Orf on improving design. Must have design complete and finalized by June 1, 2005 for a 2006 Spring Gun introduction.

Current Status

3200 style barrel hanger-Designed barrel hanger set, .040° convergance. Plans to braze 3-5 barrel sets week of 7:21. Barrels will be crowned but not tubed and shot for POI. Side Panels-Update.

5 prototype barrels with .040" versus .120" converagance built. Will ship to R. Murphy week of 8.23. Not overbored or choked, will shoot for POI/POA. Need to go to a light contour barrel, 28" 30" 32" 34" barrels, tapered rib, stepped rib, straight comb. Current design has bottom barrel 1" higher than top barrel. Need taper of approximately .014" like 3200. Barrels would be straight allowing tube sets to work.

Barrels went together well, less labor

DAT complete first week of December. T&P-barrels should not be an issue. Biggest issue is raised side panels.

Action: Make sure all future drawings/communications are funneled through Orf. (Diaz/Murphy)

Action: Checkering patterns are an option that need addressed. (Fink) Decision to stay with flat side panels.

C:\Program Files:\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 1

M332 20 gauge-2006 New Product Introduction

Current Status-Diaz

M1100 Sporting DL-B. Orf

Current Status-Make 1100 bbl with 105 ID and choke tubes, .735 with lengthened forcing cones. Goal is to have 10 barrels by September 1st. Boyds should make adjustable comb stock

Target sights

Glass beaded/shot blasted receiver

ACTION: Jeweling bolt-need to investigate bolt cosmetics. Fluting was proposed as an option. B. Orf to look into what is feasible.

Investigating ways to improve surface finish: action bars, slide, action tube, receiver with nickel Teflon finish. Polish hammer, locking block, action spring tube follower, link and hammer plunger with coating. Will have shooting prototypes by the end of September.

Action: Fink contact Kolar to have 5 adjustable comb stocks made from 1100 Sporting stocks.

Bolt-have not come up with option for jewelling or fluting. Body cote may be an option for the bolt.

Assuming cosmetics finalized by mid September, production could start end of first quarter.

Need-new cosmetics; different receiver look, new for end and checkering pattern

ACTION: Fink to supply artistic rendering for benchmark.

NEED competitive review; bring guns to next meeting.

Work with Hogue on grips-Fink to get rendering to Orf to develop.

1187 Super Magnum

Need definition on lower end of ammunition.

Action: Fink to check Owners Manual on recommendation/catalog copy/customer and consumer service/website

ACTION:B Orf to check D. Findlay research concerning low end recommendation.

2005 Spring Shotguns-Skinner, Mroz, Orf

Current Status

2005-06 SP-10 Mossy Oak Obsession October production-400 by year end 2005-07 11-87 SM NWTF-Royalties 1500 by year end Inventory at year end a concern, to date orders are less than 500 guns

2005-08 870 SM Thumbhole 850 by year end, 50 by the end of September

1st 8 stocks from Boyds have rough spots. Some issues with Boyds and their ability to supply.

2005-09 870 Exp at NWTF-Royalties **750 by year end**

925 Team NWTF guns in October

1187 Sportsman Synthetic Line -

Update \$37K total in stranded parts, \$11K is recoil pads that can be used.

ACTION: Skinner-12 gauge production schedule- 12 gauges are structured with schedules starting in October for 12/26&28 and 12/21 FR CL.

ACTION B. Orf - 20 gauge fore end status. 9 weeks & \$15K to modify 1100 20 gauge tool. Sample for ends first week of November. Scheduled to start in December.

2005 SHOT Show Specials

- NPP 2005-28 870 SP TH FR CL RAMAC 25005
- M 11-87 Premier with Wood Extra-Need Cost, Logistics, etc
- 870 FRCL Extra Barrel with Scope Mounted and Bore Sighted

C:\Program Files:TGDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 2

2006 870 Express Line

New cosmetics for Express Line (Fink)
 Black synthetic stock and fore end with overmolded inserts
 Potential laminated wood stocks with inserts-need cost and volume commitment from Boyds
 Camo guns changing to Mossy Oak Pattern-Most likely Break-Up

llion Quality - Shotguns

M1100 Sporting 28's (Orf)

Report on testing from Writers Seminar Guns and guns pulled from the warehouse.

M1187 Sportsman 12 gauge 28"

- (1) Gun with bad interceptor latch-will double feed with full mag tube
- (1) Gun that extractor fell out
- (1) Slug gun rough opening & closing; would not feed reliably or lock open reliably

Shotgun POI-Perniciaro, Orf

OBJECTIVE: Conformance to SAAMI spec

ACTION: Ilion Engineering to provide status of this project. Priority of shotguns in which to incorporate these changes first.

- 1. All 1100 Target, 1100 Classic Field and Synthetic
- 2. 11-87 Premier and SP/SPS
- 870 Wingmaster and SPS
- 4. 870 Express
- 5. SP-10

Jack Kast has picked up. Trying smaller bead to evaluate POI. Lab time is being consumed for MCS at this point of time. Late July early August at this point for an answer. By next PTM we should have results.

Standard rib and sight SAAMI- -3 1/8"

Standard rib and low sight SAAMI- +1/2"

Assuming low bead works, change all beads ASAP.

- Choke Tube Constriction/Patterning Concerns Drawings changed-Need ID Mark ACTION: B Orf to update drawings Need to add some sort of ID mark on choke tubes.
- 1187 extractor is being used in 1100 Target guns. This means old 1100 barrels will not fit new 1100's

ACTION: Perniciaro to investigate when change took place, report at next meeting, and provide plan to revert to an 1100 extractor.

Update Report-1986 DCR by Terry Douglas to change all 11-87 and 1100 (12&16ga) barrels to wide cut.

1100 Classic Field 16 gauge '02-wide cut and extractor

1100 Syn (2005 Deletion) has narrow extractor but wide barrel cut.

Moving forward-all 1100/1187 12&16 ga to have wide extractor and wide barrel cut.

C:\Program Files\\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 3

ILION BASED GENERAL TOPICS

Fore End Stickers for Wal*Mart - Mroz

- Current Status
- Implementation Dates
- BOM Updated and Structured?
- RAMACS by Model 7400-9794, 9796 870-5102, 5587 700-7512, 7474, 7478, 7480, 7514, 7476, 7516, 7482

R3 Pad on Wood Stocks-B. Orf

- Current status and implementation dates.
- 1st T&P on 700 magnum received 8.22. will submit CAR for white line spacer. Continuing to work on short stocks. Ed Owens is handling, will be at S&K at least one week per month.
- Currently working on 1100 Upland Special, Mountain Riffe.
- Will have 50 Wingmaster stocks within the next week.

Wood Stocks Dipped with Wood Pattern - B. Orf

Develop contacts to test market an 1187-Need to see some samples, may do a SHOT Show special.

ACTION: B. Orf to get contact information from S. Perniciaro and have some stocks dipped for samples.

Update for next meeting.

Botega Equipment - B. Orf

- Discuss Path Forward
- Marketing needs sample set of all rolls on hand to evaluate if any on hand are usable
- Action: Joe P. have steel plates rolled to show examples of what we have available.

NRA Licensed Guns 1187 Sportsman 870 Wingmaster 700 SPS 700 CDL

Need to know what we have now and what is needed to build new rolls in the future.

Have NRA guns to preview to customers and launch at NRA.

Action: Fink/Trull to forward artwork and complete NPP's.

ILION BASED WAL MART STRATEGY

Bunting Trull to recap strategy session with Wal Mart buyer.

Products

- 870 Express SMAG Camo (Realtree Hdwds 20-200) Fink
- 1187 Sportsman Camo (Mossy Oak New Breakup) Fink
- 700 ADL SYN Camo (Realtree Hdwds HD) Trull

ILION BASED RIFLE PRODUCTS

2005 Ilion New Rifle Programs

Model 700 Synthetic Stock Redesign Status-Mead

C\Program Files\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 4 6/12/2006

- Status Update on vendor progress
- Status update on production plans <u>Balio</u>

Custom Foam - RIM Stock for 700 LV SF

New Light Varmint stock-can spray elastomer in mold. Very durable, Can color. Could be good option for adjustable comb.

Action: Trull to schedule meeting in E'Town to discuss path forward for HS replacement.

Model 700 XCR - TriNyte Coating-G. Sietsema

- Need an update on DAT/T&P to establish material flow process with vendor.
- Need an update on competitive samples to independent test lab that we agreed to go ahead and get started per the last meeting.
- Intellectual property have we filed provisionals?
- What are lead times?
- What is final costing of TriNyte coating?

Model XR-100-Mroz

- Status Update on Gun DAT, T&P etc.
- Status Update on Owners Manual Has copy been signed off on by Dale Wills?
- Had a number of issues with failing to eject spent cases on 204 Ruger. Need to address on this gun as well as M700 s/Seven line

Model 700 SPL Fire Control - Perniciaro/Diaz

Update on testing/timing. — Perniciaro

6.8mm Rem SPC Bolt Head/Extractor Development - Perniciaro/Diaz

- Status of M700P LTR
- · Timing/Cost of Development
- Model Selection/Strategy Keep it Lean

Ilion Quality Issues - Rifles

Model 7400 Cracked Fore Ends -S. Perniciaro/Balio

· Ilion to advise of status of replacement fore ends for Rivolier.

Model 700 Fail to Eject Small Cases - S. Perniciaro

- Had a number of issues at Writer's/Sales Meeting with XR-100 failing to eject spent cases on 204 Ruger. Seems to be a common occurance on small cartridges
- · How do we address this?

Model 700/Seven Short Mag and Ultra Mag Magazine Capacities – <u>S. Perniciaro/ C. Shoemaker</u>

- Ilion to confirm that all BDL/CDL/SPS/XCR/Seven Magnum magazines are capable of holding 3 Ultra Mag or Short Magnum cartridges.
- We had addressed this back at the beginning of the year, and need to confirm before
 we launch the new line that we have this totally under control.

Model 700 Varmint Accuracy Standards - S. Perniciaro

- We need to establish a protocol to insure that our varmint rifles meet a level of accuracy that is congruent with the consumers perception that a varmint rifle should be capable of delivering sub-MOA accuracy out of the box.
- We already charge more for these guns, but we can likely get an additional premium
 if we can quarantee a level of performance.

C:\Program Files\\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 5

- We need to firm up our future business of high revenue, high margin products and
 give the consumer "insurance" in the form of a guarantee that they are justified in
 paying the premium for a varmint rifle vs. a price point rifle.
- We need to control trigger pull weights on the SPL fire control to 3 -3.5 lbs max, guarantee that the rifle shoots MOA or better and include a target in the box with the gun for 2006.

7400 SGS-New gas system - S. Perniciaro

- · Perniciaro to update on status.
- · Team to decide if we should push forward.

2006 New Rifle Products

New Model 700 Varmint Line

- · Utilizes standards set forth above with respect to accuracy and trigger pull
- Will utilize SPL firecontrol
- Will utilize new stock design outlined at recent E-Town meeting on this subject
- Discussions around how we will achieve our goals on accuracy
- Discussions around styling and cosmetics, i.e. carbon receiver with stainless barrel

Update Model Seven Wood Line for 2006

- New styling i.e CDL style? General discussion
- Wood strategy discussion S&K Boyds other supplier?
- Lead time discussion and design lead discussion.

R&D TOPICS

E-Town Development Topics

New Varmint Stock Design Diaz/Mead/Mroz

- Brief discussion on laying out preliminary design criteria
- Establish time for Trull, Mead, Mroz to travel to E-Town to meet with CAD group.

17 Hornady Mach 2 Project - Diaz/Lance

- Status on 504 accuracy testing
- Status on 597

NCAR - (New Centerfire Autoloading Rifle) - Diaz

- Status on Design
- Is there budget capital for development that has been approved?

Mayfield Topics

Model 710 Metal Receiver - Diaz/Lance

- T&P Update
- Timing for Implementation
- Must be warehousing product prior to first of year.

Model 504-T LS HB - Diaz/Lance/Trull

C:\Program Files\TGD|\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 6

- Confirm Testing schedule is on track
- Production plans
- · Accuracy Standards

Model 504 Stock Improvements - Lance

- 1/4 Sawn lumber implementation
- Wrap around fore end checkering
- Supplier plans (Boyds vs. S&K)

Model 504 Accuracy Standards - Lance/Vicars

What is path forward to achieve goals discussed with Marketing on accuracy?

Model 710 Short Action - Diaz

- . Trull discussed plans for 2006 (fall 2005 roll out) of 710 Short Action
- Includes .243 Win, 7mm-08 or .308
- · True Short Action Length
- · New Stock will allow for youth version
- · Marketing can commit to 10k units
- Diaz to update with design status

Model 597 17 HMR Accuracy in Production - Lance

· Current production status

Model 597 (6550) Cost Reduction - Lance/Vicars

- Trull has challenged plant and R&D to take \$10 cost out of the current 6550.
- Synthetic box with Vince's changes?
- Sight options?

.

Military/Law Enforcement

870 MCS-Status Update

- Israeli 120 day order with 10" bbl and threaded muzzle break choke tube, would not work. Need direction from Schoppman and Foster.
- Airforce order pending for 1150 guns.
 Trasmittal next week from R&D.

7615-Status Update - Perniciaro/Diaz

C:\Program Files\CDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006193.docPage 7