OPERATIONS COMMITTEE ILION DIVISION

()

MARCH 18, 1976

PRODUCT DEFICIENCIES KNOWN OR SUSPECTED IN 1976

MODEL 700 SAFETY LEVER

EASE OF OPERATION AND INTERESTS OF SAFE GUN HANDLING DEMAND A DESIGN THAT ENABLES A SHOOTER TO OPERATE THE ACTION WITH THE SAFETY "ON".

