B-4 - DYNAMIC DUST/DEBR. V. PRIMED CASE FIRED FAIL TO FEED DISASSEMBLED -BLOWN OUT & RE-ASSEMBLED FOLLOW DOWN ON SECOND ROUND-ICUMINATED 100L. Sear Came up BUT NOT ENOUGH TO ACCOW CONN. TO COME UP UNDER THE SEAR

ATTEMPTE TO

ATTEMPTE TO

MOVED SAFETY TO SAEF

POSITION TO FORCE

SEAR UP. UNABLE TO

MOVE SAFETY FULLY TO

SAFE POSITION.

LOWGRED F. P. TO FULL

FORWARD ROSITION

ATTEMPTED 2nd TIME
THE TIME BATE MOVED
TO SOFE ON POSITION.
AND TRIGGER BAD CONN
RETURNED TO PROPER
RECATIONSHIP UNDER SEAR.