

RECEIVING AND ESTIMATING REPORT ✓

64

INITIAL CS		CUSTOMER ORDER NO. 87563		COMMENTS			
DATE RECEIVED 11/29/91	DATE OPENED 02/05/91	DATE CODE EE 10-84	SERIAL NUMBER B6639409	MODEL AND GRADE 700 30-06.1 BDL		ORDER R 91-0364	
ACCESSORIES W/STUDS							

FROM: AHLMAN'S ROUTE 1 BOX 20 MORRISTOWN MN 55052			SHIP TO: AHLMAN'S ROUTE 1 BOX 20 MORRISTOWN MN 55052			
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 2-13-91	VIA UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *fired when closing bolt, safety sticks*

*for evaluation
Sent to J. Stekl*

MAIN FAULT: *No fault found - cannot duplicate complaint.
- suggest inspect safety assembly operation properly. Trigger pull 5 1/2 #;
- rest - left 0.015"*

butt of stock marred several places, trigger guard scratched

offer to return rifle as-is or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN 64	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90