

VINYL AND ESTIMATING REPORT

COMMENTS: L/ BLACK SLIP ON SIDE

SERIAL NUMBER 6854937	MODEL AND GRADE 700 25-06	R
--------------------------	------------------------------	---

BASE L/SIGHTS:

MN 55052

SHIP TO:
AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA 550

WRITE ☐ CLEAN/TEST

PROM. DATE ESTIMATED 9-16-91 VIA U

INSURANCE	UPS	PARCEL POST	TOTAL
☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ M

TO: Rev.

This firearm has the following defect: discharges when bolt is closed

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052

WARRANTY REQUEST

charges when bolt is closed.

Could not duplicate complaint. However, disassembly of rifle assembly has been suggested. Defect noted - 1) below spec. at 200 yds, 2) insufficient over travel. Some no load with dust and dust also. Improper maintenance.

Send repair estimate for clean and new trigger assembly (1/2 cost, as good-will gesture)

REPAIRMAN JE	PROOF	CLEAN	TEST	TARGET
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY