

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660

GENERAL CONDITION: GOOD R #: 25759

OUTSIDE WORK: SEALS BROKEN ON TRIGGER DATE: 11-6-70
ADJUSTING SCREWS. FROM: AL FISHING TACKLE, INC.
PATCHOGUE,

FIRE AMMO TYPE: — LONG ISLAND.

& CONDITION: _____ GUN #: 97965

PROOF: R.E.P. INSP.: — TEST: _____ CODE: RP = 11/67

HEADING: — GA./CAL.: 308 WIN.

BREECH OPENING: — CHECKED BY: C. PROSSER

RECOIL SHOULDERS: — APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOWING DOWN

COMMENTS: EXCESSIVE CLEARANCE BETWEEN THE TRIGGER'S
CONNECTOR (.009) ALONG WITH THE SAFETY LIFT BEING
REDUCED (.012) CREATES AN INTERFERENCE
BETWEEN SEAR AND CONNECTOR WHICH, WHEN THE
TRIGGER IS PULLED WITH THE SAFETY ON PREVENTS
THE CONNECTOR RETRACTING WITH THE TRIGGER
INTO FIRING POSITION.