RECEIVING AND ESTIMATING REPORT

Al's Gun and Reel Shop, Inc.

Remington Recommended Gunsmith 318 East Front Street

North Platte, Nebraska 69101

Phone 308/534-2660

91-05455

BONDED LOCKSMITH

2.555.

YOF

3 400 -೧೯೭೮

· ... ___

Keys Made Safes Opened Combinations Changed

GUNSMITH Parts and Service for All Popular Firearms Fishing Reels Repaired

EZ 10-75 2ND TIME IN

k REEL SHOP **YT STREET** TTE

NE 69101

Arms Service Division Remington Arms Co., Inc. Ilion, N.Y. 13357

Feb. 13, 1991

Dear Sir enclosed is a Remington 700 ADL 270 cal. SN A6212822 on two occasions this hunting season our customer reports the gun discharged upon taking the safety off. We sent this gun in a couple years for the same problem. We can't duplicate the problem and customer would like you to check it again. Please advise.

Yours truly, St. Authorities G.R. Mulholland

| ESTIMATED | VIA | |
|-----------|--------|-----|
| | UP.S | • • |
| | | 7 |
| | | |
| | • | |
| | | - 1 |
| | | - |
| | | - |
| | ** | |
| , POST | TOTAL | |
| SED | MARRED | |

- LIFE NRA -

PROOF CLEAN TEST REPAIRMAN TARGET PATTERN GALLERY TESTER DATE DATE DATE

OFFICE COPY

RD6925 REV. 7/90