

P. 11/68 GUN EXAMINATION REPORT NUMBER: 493 MODEL: 7100 414  
GENERAL CONDITION: FAIR R #: 18979  
OUTSIDE WORK: SAFETY APPEARS TO HAVE DATE: 7-23-81  
BEEN REMOVED + REASSEMBLED WRONG ANCHOR MACHINE  
FIRE ARM TYPE: NOT KNOWN FROM: + SPT GDS INC.  
4217 CANYON DR  
AMARILLO TEX  
& CONDITION: GUN #: A6407055  
PROCP: U INSP.: 62 TEST: 70 CODE: LO-2-77  
READING: OK GA./CAL.: 243  
BREECH OPENING: OK CHECKED BY: M-HARDY  
RECOIL SHOULDERS: OK APPROVED: GRL 8/2/81  
CHAMBER: OK APPROVED: GRL 8/2/81  
TEST: APPROVED: GRL 8/2/81  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: GRL 8/2/81  
BRIGHT METAL ON BBL. SLIGHT MARKS ON STOCK  
SAFETY ARM BROKEN AT THUMB PIECE  
SAFETY PIVOT PIN AND SAFETY PIVOT PIN  
RETAINER WASHER REVERSED  
COMPLAINT: FIRES ON CLOSING OF BOLT  
INCIDENT:  
COMMENTS: Unable to duplicate customer complaint.  
5 1/2# Trigger Pull .0095" seen with. Gun passes tick test.  
Replace fire control.