

New York 13357

4217 Canyon Dr.
Amarillo, Texas 79110

DATE 7-9-81

MESSAGE

In regards to a Model 600 Rifle #A6407855, our customer complains that this gun fires on closing of bolt. He wants it repaired under warranty. If this is not a warranty job, please quote cost of repair before doing the job. Thank you.

SIGNED Pat Ratcliff

REPLY

SIGNED

THIS COPY FOR PERSON ADDRESSED

READ IN THE TOP
A MESSAGE & PHONE NUMBER

COMPLAINT: FIRE ON CLOSING OF BOLT

INCIDENT:

COMMENTS: Unable to duplicate customer complaint.
5 1/2" Targis Pull .0095" seen lift. Gun passes link test.
Replace fire control.