

DAVID H. THORSNESS
JAMES M. POWELL
BRIAN J. BRUNDIN
MARCUS B. CLAPP
JOE W. HUGGLESTON
CARL J. D. BAUMAN
DENNIS M. BUNN
MARY K. HUGHES
FRANK A. PIPFNER
RALPH B. BEISTLING
R. CRAIG HESSE
ROBERT L. MANLEY
JAMES M. GORSKI
TIMOTHY R. SPRING
JAMES M. SEEDORF
RONALD E. NOEL
FREDERICK J. ODSEN
MICHAEL L. LESSMEIER**
STEVEN S. TERVOOREN
MATTHEW K. PETERSON
JOSEPH R. D. LOESCHER
KENNETH D. LOUSEY
CARL M. SUTHERLAND
JOHN B. THORSNESS



**HUGHES THORSNESS
GANTZ POWELL & BRUNDIN**

Est. 1939

ATTORNEYS AT LAW

509 WEST THIRD AVENUE
ANCHORAGE, ALASKA 99501-2273
TELEPHONE (907) 274-7822
TELECOPIER: (907) 263-9320

590 UNIVERSITY AVENUE
SUITE 200
FAIRBANKS, ALASKA 99709-3852
TELEPHONE (907) 479-3161
TELECOPIER: (907) 474-2829

GREGORY W. LESSMEIER**
JAMES N. BARRELEY
WILLIAM B. WALKER
PAUL H. CRAGG
DAVID S. CARTER
ANN S. BROWN
TIMOTHY R. REDFORD
PAUL S. WILCOX
KENNETH M. GUTSCH
CLYDE E. SNIPEN, JR.
VICKI L. BUSBARD
SHELDON S. WINTERS**
DAVID F. LEONARD
LINDA J. JOHNSON
JOHN C. WENDLANDT
PAUL K. WHARTON
CYNTHIA M. KLEPASKI
GREGORY S. FISHER
RON L. SATER
JOHN J. TIEMESSEN
MARIA M. BARNES

OF COUNSEL
JOHN C. HUGHES
RICHARD D. GANTZ

Reply to: Anchorage

**ONE SEALASKA PLAZA
SUITE 303
JUNEAU, ALASKA 99801-249
TELEPHONE (907) 586-5912
TELECOPIER: (907) 483-3020

November 25, 1992

Mr. Ed Anderson
c/o Seahawk Air
P.O. Box 3561
Kodiak, AK 99615

Re: Remington Model 700, 300. Winchester Classic

Dear Ed:

Thanks for your help and hospitality during our recent travels on Seahawk. Pursuant to our discussion, I am enclosing the name and address of the Remington Arms contact. What you described to me is a very dangerous situation and, although this is Remington's busiest time of year and it may take some months for them to return your rifle, it is very important that your rifle be returned to the factory for inspection and any necessary repairs.

As I understand the situation, you bought the rifle new for your father and it has, since that time, occasionally discharged when the safety is released. You explained that spraying the rifle with WD-40 and working the action, temporarily remedies the problem, but that it eventually reoccurs.

The weapon should be sent to:

Remington Arms Co., Inc.
Attention: Jim Stekl
Product Service
14 Hoefler Avenue
Ilion, New York 13357