DEC 1 1 305

J. A STEKL December 11, 1985

Glen E. Anson Route 3, Box 173 Perry, Ok. 73077

Remington Arms Co. Inc. Arms Service Division Ilion, New York 13357

Model 700 Cal 270 Serial No. A6360662

Dear Sir:

Twice in the 6 years I have used this rifle it fired when I released the safty.

This last time it done \$600 damage, as i had got into the prckup due to rain.

I understand this has been a problem with the Modle 700. What can be done to correct this? I have talked to the local gunsmith, he has had other inquires, But does not know what to do to correct this defect.