

Arms Service Divisions:

This box contains 2 model 700 BDL's. The right handed 700 has a broken stock. The left handed 700 was a recall gun for the trigger mechanism (Sometimes it goes off by itself) & the stock is cracking in the same place as the other. Both guns are unloaded! If there is a problem I can be reached at (318) 574-4503.

API Outdoor
C/O Greg Davis
602 Kimbrough Dr.
Tallulah, LA 71282