

P.I. NO GUN EXAMINATION REPORT NUMBER: 194 MODEL: 700 BDL

GENERAL CONDITION: GOOD R #: 31355

OUTSIDE WORK: SC, 2E M, 10-15 10050 DATE: 11-25-79

FIRE AMMO TYPE: NOT KNOWN FROM: ALLEN C. ARDELL

& CONDITION: GUN #: 328073

PROOF: (REP) INSP.: 9 TEST: 41 CODE: AR-3-68

HEADING: OK GA./CAL.: 308

BREACH OPENING: OK CHECKED BY: M-HARDY

RECOIL SHOULDERS: OK APPROVED: ADH 11/4/80

CHAMBER: OK APPROVED: PLJ 11/4/80

TEST: APPROVED: E.F.B. 1-6-8

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: WAW 1-4-80

SMALL DENTS IN WOOD STOCK

See Safety Cam extremely rusty - Rust on trigger connector

COMPLAINT: FIRE WITH SAFE IN OFF POS WHEN

TOUCHING BOLT HEADS

INCIDENT:

COMMENTS: Unable to duplicate customer complaint.

- Investigation of fire control shows rust about trigger assembly components which may have contributed to incident.

Replace fire control at no charge