

ORDER
R 91-26294

DATE
25-06

BDL

ER, DUANE
X 96A
TY

NC

68355

ESTIMATED

VIA

UPS

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

INSPECT

F1

F2

F3

F4

F5

it was made
suggested
advising, and
to 22 pounds

at present
can offer a
in account at
me of good-will.

Bruster's Place
RR #1 Box 96A
Falls City NE 68355
8-47-074-01-9G-11833

D. Ambrose

GALLERY TESTER

DATE

DATE

DATE

TARGET

PATTERN

DATE

DATE

Remington
Recently spoke with rep of
your company about enclosed Rifle
It was advised to send to this address
for repair.

Recap of problem:

Past couple years gun has discharged
on 3 occasions w/o pulling trigger.

Twice as gun was being placed in
Fire position from safe and once when
bolt was raised slightly to unload.

Owner of gun was trying to show me
what happens w/ the unloaded weapon &
after placing gun on & off safety App 10
times firing pin did fall on the empty
chamber. We then tried for App 12 hr
to get it to do it again but was unsuccessful.

Owner did state that on several occasions when
gun was empty ~~this~~ this would happen either
when placing gun in Fire position or when starting
to bolt gun.

ThankX

Duane Ambrose
RR #1 Bx 96A
Falls City NE 68355
PBX 402-245-5014