

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 11/05/90	DATE OPENED 11/06/90	DATE CODE WQ 8-78	SERIAL NUMBER A6605362	MODEL AND GRADE 700 308 BDL		ORDER R 90-291	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:

**BARRONS FISH & HUNTING
1725 HARDEN ST
COLUMBIA SC 29204**

SHIP TO:

**BARRONS FISH & HUNTING
1725 HARDEN ST
COLUMBIA SC
29204**

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

accidental discharge

MAIN FAULT

Trigger assembly is contaminated with gunning, sticky residue - when trigger parts are not moving properly. Trigger and semi-automatic move very slowly. Rifle has not been properly maintained.

PARTS

*Offer complete new trigger assembly
but \pm internal pin as gesture of
good-will.*

Rifle is 12 years old

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PPS 00347