

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 92-269

INITIAL
JJM

CUSTOMER ORDER NO.

ATT R POTTER

92-26939

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/04/92

12/10/92

AQ 3-7B

A6582807

700 22-250

CLASS I

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

BARTLETT, R L
RT 1 BOX 91-AA
LEDBETTER

TX 78946

SHIP TO:

BARTLETT, R L
RT 1 BOX 91-AA
LEDBETTER

78946

CUST NO: 071634 C-D.DL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

☒

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				25.00
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt of rifle, we could not duplicate customer alleged problem. However, it was noted that the trigger assembly was contaminated with grease. Amount of dirt / dust. The resultant result on adjustment was trigger pull - 5 1/2 pounds, zero - 1975 mfg. 1978

PARTS

COMMENTS

Based on condition of trigger assembly, offer new trigger assembly at 1/2 cost, as a gesture of good will. Customer approved for price 12/29/92 for new style trigger assembly without shock.

RECEIVED	PROOF	CLEAN	TEST	TARGET	PA
		✓			
GALLERY TESTER	DATE	DATE	DATE	DATE	DA

OFFICE COPY

RD6925 RF