

cust. Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW R #: 000219

OUTSIDE WORK: No DATE: 1-4-72

FROM: BAY CITY HDQ. CO.

FIRE AMMO TYPE: - BAY CITY, MICH.

& CONDITION: _____ GUN #: 6425267

PROOF: RE.P.-K ^{ASSEMBLER C} INSP.: 74 TEST: 87 CODE: CU = 4/71

HEADING: O.K. GA./CAL.: 300 WIN. MAG.

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS.

TRIGGER PULL 5 POUNDS, HORIZONTAL ENGAGEMENT .020

(MIN. IS .020) VERTICAL ENGAGEMENT .035 (MIN. IS .015)

TRIGGER DOES NOT RUB ON TRIGGER GUARD.

COMPLAINT: "WHEN SAFETY IS PULLED BACK GUN FIRES WITHOUT PULLING TRIGGER."

INCIDENT: FOLLOW DOWN.

COMMENTS: CAN FIND NO DEFECT WHICH MIGHT LEAD TO THE CUSTOMER'S MALFUNCTION. HIS MALFUNCTION NOT DUPLICATED.