

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
92-06262INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED

02/20/92

DATE OPENED

02/28/92

DATE CODE

BY 1-74

SERIAL NUMBER

6690866

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

RDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

BENTZE, WILLIAM
1238 EAST 27TH STREET
ERIE

PA 16504

SHIP TO:

BENTZE, WILLIAM
1238 EAST 27TH STREET
ERIEPA
16504

CUST NO: 058821 C.O.D.

ACCOUNT NUMBER

063103

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

3-23-92

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

3

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT:

Sent to J. Stekl for evaluation
Examination of rifle and trigger assembly disclosed no problems - trigger as
and safety operate properly. It was noted that the over-travel has been improv-
advised but not fixed (insufficient over-travel), however, this did not affect
operation. Cannot duplicate complaint.
Trigger pull 42 pounds; over-let - 0.105"
Wood marked, metal marked

PARTS

COMMENTS

We can offer to properly adjust
over-travel and return, or to install
a new trigger assembly at a normal
cost as a gesture of goodwill if
that will better restore confidence in
the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8

PPS 00432