

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R92-17282

INITIAL
FPS

CUSTOMER ORDER NO.
1962

DATE RECEIVED
08/14/92

DATE OPENED
08/28/92

DATE CODE
DH 9-87

SERIAL NUMBER
B6891806

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

RS

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

BILLS SPORTING GOODS
724 MAIN ST
LOMIRA

WI 53048

SHIP TO:

BILLS SPORTING GOODS
724 MAIN ST
LOMIRA

WI
53048

CUST NO:007455 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

As above - as worn has completely misadjusted the trigger assembly - excessive over-travel & in interaction spring force trigger pull is only 1 1/2 pounds!

main left = 0.14"

ARTS

COMMENTS

Quote new trigger assembly at 1/2 normal cost as gesture of good will. Tell customer to keep his hands off adjustments on new trigger assembly !!!

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92

PPS 00491