

Bi-Mart

5976 SW 185th

Aloha OR 97007

Dir Sir

The Customer claims that the Rifle
Started firing when the bolt is locked
into place when he last purchased it
Three years ago. If possible please check
the Rifle and determine if it is a
Workmanship Defect. Then contact either
Linda or Todd at (503) 649-6530
For further instruction.

Thank you
Jill Winkler