

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R 94-13571	
INITIAL FPS		CUSTOMER ORDER NO.					
DATE RECEIVED 04/19/94	DATE OPENED 04/20/94	DATE CODE PH 6-87	SERIAL NUMBER B6867477	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN ADL		
ACCESSORIES W/STUDS		SCOPE BASE		LASIGHTS			
FROM: BLOOM, ROBERT R 6 BOX 169 LITTLE FALLS MN 56345				SHIP TO: BLOOM, ROBERT R 6 BOX 169 LITTLE FALLS MN 56345			
CUST NO: 096230 C.L.O.D.							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		WRITE ☐		PROM. DATE	ESTIMATED
						VIA	UPS
GUN CONDITION						REPAIR CHARGE 20.00	
☐ NEW						EXCISE	
☐ LIGHTLY WORN						TAX	
☐ WORN						INSURANCE	
☐ VERY WORN						UPS	
☐ UNREPAIRABLE						PARCEL POST	
☐ MARRED						TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4			E3	F3	
REC. ASSY.		B5			E4	F4	
WOOD				D3	E5	F5	
METAL			C2				
MAIN FAULT <i>Gun & trigger assembly removed, unable to close bolt upon reset. Trigger assembly jammed up from wrong adjustment and poor maintenance. Gun also had good change trigger but 44.00. That assembly appears to have been repaired. Gun test OK.</i>							
COMMENTS <i>Gun & trigger assembly removed and then returned at the normal adjustment cost, in good condition.</i> <i>Go ahead</i>							
REPAIRMAN JAL				PROOF	CLEAN	TEST	TARGET
GALLERY TESTER				DATE	DATE	DATE	DATE

to A.S 5/19/94