

Remington Arms
MayfieldQuality Manual 6-2
Appendix A
Form C-1036

NO MATERIAL CERT

First Article Inspection -Mayfield Results

Part Number
Part Name300464
SEAR RETAININGDrawing #
Rev. LevelB-300464
DVendor
Date Received
Lot #PIN
NATIONAL METAL PROC.
8-2-00
N/A

500 PCS

SAMPLES

Bottom

Average Min Max

#	Feature Name	#1	#2	#3	#4	#5				
1	R15N 88-92	91.5	91.3	91.0	90.7	90.9	#DIV/0!	0.0000	0.0000	Rockwell
2	$\phi .200 \pm .005$	.201	.201	.200	.202	.201	#DIV/0!	0.0000	0.0000	Caliper
3	$.035 \pm .005$	.037	.037	.038	.039	.037	#DIV/0!	0.0000	0.0000	
4	$.119 \pm .001$	.117	.119	.118	.119	.119	#DIV/0!	0.0000	0.0000	
5	$\phi .124 \pm .001$	.125	.126	.124	.125	.124	#DIV/0!	0.0000	0.0000	85
6	$.470 \pm .005$	.472	.472	.468	.469	.470	#DIV/0!	0.0000	0.0000	
7	$.530 \pm .005$	.530	.529	.527	.530	.529	#DIV/0!	0.0000	0.0000	
8	$.020 \pm .005$	.019	.020	.020	.021	.019	#DIV/0!	0.0000	0.0000	
9	$.040 \pm .005$	.040	.039	.037	.037	.042	#DIV/0!	0.0000	0.0000	
10	R .016	.085*	.010	.010	.010	.010	#DIV/0!	0.0000	0.0000	
11	$.015 \times 45^\circ$	.009	.006	.010	.006	.010	#DIV/0!	0.0000	0.0000	
12		45°	45°	45°	45°	45°	#DIV/0!	0.0000	0.0000	
13							#DIV/0!	0.0000	0.0000	
14							#DIV/0!	0.0000	0.0000	
15							#DIV/0!	0.0000	0.0000	
16							#DIV/0!	0.0000	0.0000	
17							#DIV/0!	0.0000	0.0000	
18							#DIV/0!	0.0000	0.0000	
19							#DIV/0!	0.0000	0.0000	
20							#DIV/0!	0.0000	0.0000	
21							#DIV/0!	0.0000	0.0000	
22		* BUMP	ON RADIUS				#DIV/0!	0.0000	0.0000	
23							#DIV/0!	0.0000	0.0000	
24							#DIV/0!	0.0000	0.0000	
25							#DIV/0!	0.0000	0.0000	
26							#DIV/0!	0.0000	0.0000	
27							#DIV/0!	0.0000	0.0000	
28							#DIV/0!	0.0000	0.0000	
29							#DIV/0!	0.0000	0.0000	
30							#DIV/0!	0.0000	0.0000	

BUMP
IN RADApproved By
Rejected By

Donna GREGG

Date
Date

8-2-00

Revised By: M. Goelmboski
Revision Date: 2/14/00

FirstArticleInspection

ET06398