

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-09969

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
04/14/93

DATE OPENED
04/15/93

DATE CODE
LB 2-81

SERIAL NUMBER
R6237379

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL/LH

ACCESSORIES

W/STUDS

FROM:

BONURA, TONY
3112 KANSAS AVE
KENNER

LA 70065

SHIP TO:

BONURA, TONY
3112 KANSAS AVE
KENNER

LA
70065

CUST NO: 07B065 C.D.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

25.

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2		E1		F1
BOLT ASSY		B3		E2		F2
BARREL ASSY		B4		E3		F3
REC. ASSY		B5		E4		F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Unable to duplicate customer concern.
However, examination revealed sluggish movement of trigger & bolt stop action. Heavy coating of dirt, grime, & debris in action and trigger assembly.

PARTS	COMMENTS
4/28 558 250 358	Examine complete trigger assembly and clean action at 1/2 normal replacement cost as per quote of 5/4/93
5/3/94	Go ahead per phone 5/4/93
Phone # 504-736-6586	
Charge Credit Card	
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTER	DATE