

Den 13 - T.P 4<sup>th</sup>  
S.L.012

12/31

Rust On Trig. Assy. Bedding Compound  
On Trig. Assy. Barreled Action Appears  
To Have Been Put In Another Stock  
And Bedded  $\frac{1}{2}$  Price Bedding  
Sealant Missing On Fire Compound  
Control

Martin