

# RECEIVING AND ESTIMATING REPORT

|                       |                    |           |               |                 |            |
|-----------------------|--------------------|-----------|---------------|-----------------|------------|
| CUST NO: 050232 C.O.D |                    | COMMENTS  |               | STK: 10         |            |
| TIAL                  | CUSTOMER ORDER NO. |           |               |                 |            |
| CS                    |                    |           |               |                 |            |
| TE RECEIVED           | DATE OPENED        | DATE CODE | SERIAL NUMBER | MODEL AND GRADE | ORDER      |
| 9/27/91               | 10/02/91           | WU 8-71   | 6471674       | 700 30-06 BDL   | R 91-19510 |
| CESSORIES             | W/STUDS            |           |               |                 |            |

L/REAR SIGHT

|                                                                            |                                                                            |
|----------------------------------------------------------------------------|----------------------------------------------------------------------------|
| OM:                                                                        | SHIP TO:                                                                   |
| BOURGEOIS, RODNEY<br>6 LA COMBE HARBOR LA<br>PO BOX 907<br>LA COMBE<br>USA | BOURGEOIS, RODNEY<br>6 LA COMBE HARBOR LA<br>PO BOX 907<br>LA COMBE<br>USA |
| LA 70445                                                                   | LA 70445                                                                   |

|              |                    |                                |            |            |           |     |
|--------------|--------------------|--------------------------------|------------|------------|-----------|-----|
| COUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | CLEAN/TEST | PROM. DATE | ESTIMATED | VIA |
|              |                    |                                |            |            | 10/2/91   | UPS |

|            |     |           |     |             |       |
|------------|-----|-----------|-----|-------------|-------|
| AIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|            |     |           |     |             |       |

JN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: *cc*  
 1) When attempting to move the safety from off to fire and a round is in the chamber, the weapon automatically fires. 2) After firing a round and another is loaded the weapon may or may not fire as soon as the bolt is fully closed.

*cannot duplicate complaints. However, it was noted upon removal of action from stock, the trigger assembly has some rust (both internally & externally) upper assembly has been improperly adjusted out of factory - excessive overtravel upper pull measured at 3 pounds; rear lift "007"*

*Due to condition of present trigger assembly, and customer's ~~comment~~ comments re: bolt-lock, offer new-style (no bolt-lock) trigger assembly at 1/2 normal cost, as a gesture of good will.*

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| <i>NR</i>      |       |       |      |        |         |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |
|                |       |       |      |        |         |

OFFICE COPY

RD6925 REV. 7/90

PPS 00611