

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R# : 22615
OUTSIDE WORK: NO DATE: 11-8-71
FIRE: NO FROM: BOWLING, INC.
FIRE: NO WHITE SULPHUR SPRINGS,
FIRE: NO WEST VIRGINIA.
& CONDITION: _____ GUN # : 6320972
PROOF: R.E.P.E INSP.: 73 TEST: 87 CODE: AT=3/70, WT=8/70
HEADING: _____ CAL./CAL.: 300WIN MAG
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN COMPONENTS

COMPLAINT: "GOES OFF WITHOUT PULLING THE TRIGGER"

INCIDENT: FOLLOWS DOWN (VERIFIED BY WRITER)

COMMENTS: TRIGGER FULL 2 1/2 POUNDS, SEAR-CONNECTOR ENGAGEMENT .005 (MIN. IS .015) NO INDICATION OF GUNNER RE-ADJUSTING.

APPARENTLY ENGAGEMENT OF SEAR AND CONNECTOR UNDER MIN. IN COMBINATION WITH THE LIGHT TRIGGER FULL CAUSED THE FOLLOW DOWN.