

B-15	REM R30065 180GR	40							
	REM R30067 220GR	40							
	REM UMC L30062 150GR	40	NO MALFUNCTIONS						
	REM PRT3006B 165GR	40							
	REM R30063 150GR	40							
	TOTAL	200	0	0		0	0		0
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN MAG BOX	MISFIRE	BOLT CAME OUT
B-16	REM R30065 180GR	40							
	REM R30067 220GR	40							
	REM UMC L30062 150GR	40							
	REM PRT3006B 165GR	40							
	REM R30063 150GR	40	1						
	TOTAL	200	1	0		0	0		0
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN MAG BOX	MISFIRE	BOLT CAME OUT
B-17	REM R30065 180GR	40							
	REM R30067 220GR	40							
	REM UMC L30062 150GR	40	NO MALFUNCTIONS						
	REM PRT3006B 165GR	40							
	REM R30063 150GR	40							
	TOTAL	200	0	0		0	0		0
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN MAG BOX	MISFIRE	BOLT CAME OUT
B-18	REM R30065 180GR	40							
	REM R30067 220GR	40							
	REM UMC L30062 150GR	40							
	REM PRT3006B 165GR	40							
	REM R30063 150GR	40				1			
	TOTAL	200	0	0		1	0		0
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN MAG BOX	MISFIRE	BOLT CAME OUT
B-19	REM R30065 180GR	40							
	REM R30067 220GR	40							
	REM UMC L30062 150GR	40	NO MALFUNCTIONS						

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0096937

ETE00002846