

	REM 27830 220GR	100									
	REM UMC 23899 150GR	100									
	REM 29178 165GR	100									
	FED 3006B 180GR	100									
	FED P3006Q 165GR	100						1			
	FED P3006G 150GR	100				1				1	
	WIN SHV30064 180GR	100									
	WIN SBST3006A 168GR	100								2	
	WIN S3006XB 150GR	100	2								
	TOTAL	1000	2			1		3		3	
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE	BOLT CAME OUT	
B-14	REM 27828 180GR	100						2			
	REM 27830 220GR	100									
	REM UMC 23899 150GR	100									
	REM 29178 165GR	100									
	FED 3006B 180GR	100									
	FED P3006Q 165GR	100						1			
	FED P3006G 150GR	100	1								
	WIN SHV30064 180GR	100	1	1							
	WIN SBST3006A 168GR	100									
	WIN S3006XB 150GR	100									
	TOTAL	1000	2	1				3			
NOTE: BOLT HANDEL BROKE OFF AFTER 1000 RD ENDURANCE WHILE TAKING HEAD SPACE											
GUN	AMMO	ROUNDS	F.T.E.	B.O.R.	STEM HIGH	STEM LOW	STRAIGHTEN	MAG BOX	MISFIRE	BOLT CAME OUT	
B-15	REM 27828 180GR	100	1					2			
	REM 27830 220GR	100	1								
	REM UMC 23899 150GR	100	1								

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060005700

ETE00002849