

P.I. 4/25 GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: M 700 ADL  
 GENERAL CONDITION: Good R #: PA.  
 OUTSIDE WORK: Trigger Engagement & Pin C DATE: 12/1/71  
Broken FROM: Thomas Brown  
 FIRED AMMO TYPE: \_\_\_\_\_  
 & CONDITION: \_\_\_\_\_ GUN #: 6372712  
 PROOF: ✓ INSP.: ✓ TEST: ✓ CODE: DT 9/70  
 HEADING: Not checked GA./CAL.: 30/06  
 BREECH OPENING: \_\_\_\_\_ CHECKED BY: Harry R. R.  
 RECOIL SHOULDERS: \_\_\_\_\_ APPROVED: [Signature]  
 CHAMBER: \_\_\_\_\_ APPROVED: Burn 12/1/71  
 TEST: Place - Examined in attorney's office APPROVED: Atty. Gen. 12/1/71  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_  
Trigger Engagement Screw seal and stake  
broken



COMPLAINT: Fires when safe is released.

INCIDENT: Fired on releasing safe. Shot operator.  
lost

COMMENTS: Screw Connector engagement OK. Slight Trigger Hammer  
protrusion on left side of bolt. Slight engagement  
of F.P. Head to frame. "Shift acceptable" reading on "notch"  
of Screw & Connector; Trigger face in frame; Trigger  
Engagement Screw seal and stake broken, screw driven  
into frame. Other adjustment screws sealed. Trigger  
Engagement Screw rotated when Trigger Pin trapped with  
hammer. Incident could not be 100% fixed.