

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CLOSED

SERIAL NUMBER

MODEL AND GRADE

17 0729

10/31/77

11/3/81

3240-110

700 ZH14A1-100

ACCESSORIES

W7STUDS

FROM:

BURNS, JOHNNY
3336 COUNTRY CLUB DR
CHARLOTTE NC 28205

SHIP TO:

BURNS, JOHNNY
3336 COUNTRY CLUB DR
CHARLOTTE NC 28205

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

J. P. FOSTER
5018 CARRILION DR.
CHARLOTTE, NC 28226

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☒ LIKE NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"GUN FIRED WHEN SAFETY WAS PUSHED OFF"

MAIN FAULT

Trigger assembly rusted from unknown source. Internal parts not moving properly.

Note: barrel rusty at muzzle point location and, rear guard assembly rusty. Appears rifle was wet at some time & not properly maintained.

PARTS

Per J. Foster (Sales Rep) instructions, rifle to be return shipped to him via U.P.S. NEXT DAY

Replace Trigger assembly at no-charge as gesture of good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

RD6925 REV. 7/90

PPS 00790