

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: GOOD R #: 000999

OUTSIDE WORK: NO DATE: 1-12-72

FIRE AMMO TYPE: _____ FROM: CADDIE LABAR'S

& CONDITION: _____ DISTR. CO. DALLAS, PENN.

PROOF: R.E.P. INSP.: ? TEST: 79 GUN #: 232943

HEADING: O.K. CODE: WN = 8/66

BREECH OPENING: _____ GA./CAL.: 280 REM.

RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTS. TRIGGER PULL FOUR
POUNDS, ENGAGEMENT .015, TRIGGER BINDING ON GUARD
SLIGHTLY. GREASE-DIRT COATING ON HIDDEN PARTS
INCLUDING INSIDE & OUTSIDE OF TRIGGER ASSEMBLY.

COMPLAINT: SOMETIMES IT WILL FIRE, OTHER TIMES IT WON'T, SOMETIMES
IT WILL BE A DELAYED FIRING.

INCIDENT: SEAR DOES NOT RELEASE FIRING PIN.

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS DUPLICATED WITH
STOCK IN PLACE BUT WORKED O.K. WITH STOCK OFF.
APPARENTLY THE TRIGGER-TRIGGER GUARD BIND
COMBINED WITH THE TOO HEAVY LUBRICATION WAS
THE CAUSE OF HIS TROUBLE.