

After cleaning
and reassembling, the
pin did not disengage
moving the safety to Fire.

I'm still concerned as to
whether this rifle is safe
to shoot so I'm returning
it for your inspection.

Could you change bolt, to
be able to open while safe
is on, similar to newer
700 models, I understand there
is a charge for this.

If there is a charge to
repair rifle please bill me
C.O.D.

Thank you

BOB CAMBURN
1039 West Ave.
609-398-6441 OCEAN CITY, N.J. 08226

TO: Remington
14 Hoesie
ILLION, N.J. 10
Service Dis.