

RECEIVING AND ESTIMATING REPORT

CUST NO: 051966 C.O.D		COMMENTS		STEAK	
INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 0/25/91	DATE OPENED 10/30/91	DATE CODE DZ 9-75	SERIAL NUMBER A6206590	MODEL AND GRADE 700 270	ORDER R 91-21859
ACCESSORIES		W/STUDS		HARD CASE	

FROM:

CARIS, NICK
P O BOX 2163
BUCKHANNON
USA

WV 26201

SHIP TO:

CARIS, NICK
P O BOX 2163
BUCKHANNON
USA

WV
26201

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11/5/91	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	----------------------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION:

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"When putting a shell in the chamber, the gun fires"

FAULT

Cannot duplicate complaint - firing pin could not be made to fall fully cycling bolt. However, it was noted that trigger assembly had been adjusted outside factory - trigger pull below our minimum performance to be 2 3/4 pounds. Trigger actuation was not consistent because of light pull - rear lift 0.007"

We can re-adjust trigger assembly to heavier pull weight, or, offer to install new trigger assembly at 1/2 normal cost, as a gesture of goodwill, if this will better restore confidence in the rifle.

REPAIRMAN JTM	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90

PPS 00888