

DEAR SIR,
REIVING AND ESTIMATING REPORT

203-482-7947

MR. CARMINE P. CONTI
85 PICCADILLY AVE.
TORRINGTON, CT 06790

DEAR SIR,

THE ENCLOSED FIREARM (MODEL 700 BOL 270 CAL.) WAS PURCHASED NEW IN 1977
AND HAS PERFORMED WITHOUT MALFUNCTION UNTIL THIS DATE.

ON SEPTEMBER 30, THIS YEAR, WHILE AT THE TARGET RANGE, THE RIFLE
DISCHARGED WHEN THE SAFETY LEVER WAS MOVED FORWARD WITHOUT EVER
TOUCHING THE TRIGGER.

AFTER FOUR MORE ATTEMPTS OF MOVING THE SAFETY FORWARD, THE
RIFLE DISCHARGED ON EVERY INSTANCE.

PLEASE NOTIFY ME BEFORE REPAIRING, WHAT WILL BE NECESSARY FOR
THE RIFLE TO OPERATE CORRECTLY.

SINCERELY,

Carmine P. Conti

CARMINE P. CONTI