

116-20 Atlantic Avenue  
RICHMOND HILL, NEW YORK 11419  
(718) 847-7661  
FFL 6-11-041-01-3J-05238  
N.Y.C. 55

|                                 |                                   |                                       |                                           |
|---------------------------------|-----------------------------------|---------------------------------------|-------------------------------------------|
| SOLD BY                         |                                   | DATE                                  |                                           |
| NAME                            |                                   | 4/20 1983                             |                                           |
| ADDRESS                         |                                   | PHONE                                 |                                           |
| CITY                            |                                   |                                       |                                           |
| <input type="checkbox"/> CASH   | <input type="checkbox"/> CHARGE   | <input type="checkbox"/> MDSE. RETD.  | <input type="checkbox"/> PREVIOUS BALANCE |
| <input type="checkbox"/> C.O.D. | <input type="checkbox"/> PAID OUT | <input type="checkbox"/> PD. ON ACCT. |                                           |

Remington Arms Service  
14 Hoefler Ave  
Plain NY 13357

Dear Sir

Enclosed is a Rem  
700 30-06 # B6814615.  
The customer is having  
hard fires with factory  
ammunition. I believe the  
problem is in the trigger  
it is a dangerous condition.  
Please repair and test  
fire.

Thank You  
H. Betzger

Thank You!

RECEIVED BY

PRODUCT 690-1  Inc., Groton, Mass. 01471. To Order PHONE TOLL FREE 1-800-225-6380