

RRR-114

P.I. YES GUN EXAMINATION REPORT NUMBER: 475

MODEL: 700

GENERAL CONDITION: FAIR

R #: 17327

OUTSIDE WORK: STOOD 2000

DATE: 7-1-81

FIRED AMMO TYPE: REM PETERS

FROM: DEMMIS CLARK

& CONDITION: 7 SPENT CLSBS

REPAIRS V/E

PROOF: L DISP.: 9 TEST: 87

GUN #: 31419512

HEADING: OK

CODE: 54471

BREECH OPENING: OK

GA./CAL.: 222 REM

RECEL SHOULDERS: OK

CHECKED BY: M-H 804

CHAMBER: OK

APPROVED: 7/2/81

TEST: _____

APPROVED: 7/2/81

APPROVED: 7/2/81

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SMALL MARKS ON STOCK JERKING UP BY 3" WORK
BOLT PLUG WANTED.

COMPLAINT: NO INFORMATION

INCIDENT: _____

COMMENTS: TRIGGER ADJUSTMENT CREW SET OUT A SPECIFIC TRIGGER.

TRIGGER ADJUSTMENT & OVERHAUL SCREWS - SEALANT MISSING
INDICATING ADJUSTMENT OUTSIDE OF FUNCTION. TRIGGER BUILT
2# out of Remington Series 3# to 5#.