

That much.

The Gun Instructors at
Montgomery Tech. in Troy, N.C.
has tried to fix it & advised
me to write Remington &
see if a new Bolt would
solve the problem?

Please help me with this problem
& a dangerous one as I am
afraid to use gun any more
& it has been such a good one.


Thanks -

John D. Currie
Rt.#1 Box 105 -
Mt. Gilend, N.C. 27506

Remington - Model 700 BDL
AUG - 7 1983 - Bolt Action
S.C.# 349138

J.A. STEKL

Problem - Pull Trigger - Nothing
- Then a few seconds - Gun
goes off -
Bolt Gun with out touching
Trigger & Gun will fire -
Does Not Do This Next
5 to 20 Times Then
Starts going off again
Very Dangerous



Every Gunsmith ~~around~~ ~~had~~
tried & said they had it fixed
only for it to happen again
After I shot it a few times -

Although Gun is several years
old - it is only used Deer
Season & has not been shot →