

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 94-06095

INITIAL JJM CUSTOMER ORDER NO 3059

DATE RECEIVED 02/11/94 DATE OPENED 02/18/94 DATE CODE RI 11-00 SERIAL NUMBER C6312872 NEW SERIAL NUMBER MODEL AND GRADE 700 7MMAG BDL

ACCESSORIES W/STUDS L/SIGHTS

*Product Service*

*NO F. SUPPLY*

FROM:

CUSTOM GUN WORKS  
4952 JOHNSTON ST  
LAFAYETTE LA 70503

SHIP TO:

CUSTOM GUN WORKS  
4952 JOHNSTON ST  
LAFAYETTE LA 70503

*Send quote Hold for reply*

CUST NO: 001976 ILIONL

*COO*

ACCOUNT NUMBER 068103 ACCOUNT NUMBER N/C PROM. DATE ESTIMATED 3/26/94 VIA UPS

- NEW
- LIGHTLY WORN
- WORN
- VERY WORN
- UNREPAIRABLE
- MARRED

*\$20 trigger Assy  
5 test  
8 shipping  
\$33.00*

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			F1	F2
BOLT ASSY.						F3
BARREL ASSY.		B4	D1		E3	F3
REC. ASSY.		B5				
WOOD			C1	D3	E5	F5
METAL			C2			

*Gun fired when moving safety to fire position, and fails to eject. Customer said that the trigger had not been altered. (see attached letter)*

MAIN FAULT

*Gun mfr. 1/88 unable to duplicate customer concern, however trigger has been adjusted outside the factory. Both pounds pull and overtravel screws had set screws removed and were backed out. Replace trigger Assy. at a special price strictly as a gesture of good will. We do not recommend that the trigger be adjusted outside of the factory.*

PARTS

*Trigger Assy. Complete*

COMMENTS

*Trigger pull measured 2 1/2 lbs as Rec'd.*

REPAIRMAN <i>JSB</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94