



Nautilus® SPORTS/MEDICAL INDUSTRIES, INC.

Box 160, 709 Powerhouse Road
Independence, Virginia 24348

(703) 773-2881

7 Dec 89

Remington Arms Service Div.
ILion, NY 13357

Mr. Cole

As per our conversation of Early Nov.
I'm sending to you, for repair (1) Rem. Model #7
7mm x 08 rifle with defective trigger mechanism.
When one round is fired and another round is
chambered the ~~SECOND~~ round fires without
pulling the trigger. Your help repairing
this serious safety hazard will be appreciated

Return To:
Bobby C. Delp
Rt. 2 Box 235
Independence, VA
24348

Thank you.
Bobby C. Delp