

P.I. YES GUN EXAMINATION REPORT NUMBER: 314 MODEL: 700 ADL

GENERAL CONDITION: FAIR R #: 32622

OUTSIDE WORK: SIGHTS REMOVED DATE: 12-3-80

SWIVEL STUDS ADDED FRONT Bearing Pad
removed in stock. FROM: DE MARCO SPT. GOODS
FIRE AMMO TYPE: NOT KNOWN 200 N. SIDE DRIVE
RENNINGTON VERM

& CONDITION: _____ GUN #: B6217994

PROOF: REP INSP.: 122 TEST: 82 CODE: PA 3=11-80
EA 3=10-80

HEADING: _____ OK GA./CAL.: 270

BRESCHE OPENING: _____ OK CHECKED BY: M HAROY

RECOIL SHOULDERS: _____ OK APPROVED: GH 1/13/81

CHAMBER: _____ OK APPROVED: AG 1/13/81

TEST: _____ APPROVED: JAS 1/13/81

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BRIGHT MARKS ON TOP REC

EXTRACTOR BROKEN RIGHT SIDE OF RIVET

COMPLAINT: RIFLE HAS FIRING PROBLEM

INCIDENT: SHOT HOLE IN TRUCK - FSR

COMMENTS: Tugger pull 3 3/4", Passed Truck test

Unable to verify customer complaint. Gun
appears to be normal.