

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R92-27011

INITIAL CUSTOMER ORDER NO.

DATE RECEIVED 2/05/92	DATE OPENED 2/10/92	DATE CODE CU 4-71	SERIAL NUMBER 6435318	NEW SERIAL NUMBER	MODEL AND GRADE 700 6MM REM ADL
ACCESSORIES W/STUDS		SCOPE BASE			

FROM:

DICK'S GUN REPAIR SHOP  
175 LIBERTY SPG RD  
SUFFOLK VA 23434

SHIP TO:

DICK'S GUN REPAIR SHOP  
175 LIBERTY SPG RD  
SUFFOLK VA 23434

CUST NO: 007011 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	-------------------	--------------------------------	------------	------------	-----------	------------

UN CONDITION	REPAIR CHARGE
<input type="checkbox"/> NEW	EXCISE
<input type="checkbox"/> LIGHTLY WORN	TAX
<input type="checkbox"/> WORN	INSURANCE
<input type="checkbox"/> VERY WORN	UPS
<input type="checkbox"/> UNREPAIRABLE	PARCEL POST
<input type="checkbox"/> MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
DLT ASSY.		B3			E2	F2
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

Unable to duplicate Complaint. However, it was noted that the trigger assembly had been adjusted outside the factory (no force on front of connector) and trigger pull below factory specifications. Trigger Pull 1 1/4 pounds, 5000 ft. lbs. Gun condition good, brown residue found on bolt stop release. rifle only 1971

Based on condition of trigger assembly and the fact that the new engagement has improved with, offer a new trigger assembly at 1/2 normal cost, was given of good.

REPAIRMAN J.R.	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92