

To whom it may concern:

Enclosed you will find A Remington  
XP-10.0 .35 REM serial number B7520484.  
The gun was purchased 3/17/88 from  
Sheeters Supply Holcomb, NY.

The gun had been fired approximately  
35 times before it blew out on 4/30/88.  
Of the 35 rounds fired thru the gun  
the last 10 rounds were handloads. These  
handloads had been carefully researched and  
fired in 3 different Thompson Contenders  
previously with no adverse results. The  
load consisted of 43 grains of H322 with  
A 180 grain Speer flat point bullet and large  
rifle magnum primers. The brass used was  
once fired Remington brass which had each been  
checked for length. The individual charges had