

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.		COMMENTS ATT ROGE POTTER			
ED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
/88	10/03/88	LI 2-76	A6252163	600 6MMREM MOHAWK	R 88-25995
W/STUDS					

PAUL EDWARDS 6409 E. FAIRFIELD MEAS, AZ. 85205			SHIP TO: PAUL EDWARDS 6409 E. FAIRFIELD MEAS, AZ. 85205		
NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS

AGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-----	-----	-----------	-----	-------------	-------

CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRIED

REQUEST

... because of pushing the safety forward, the gun would fire.

... slide trigger assembly - improperly adjusted outside factory - which causes engagement!

Replace with new slide assembly at no-charge per P. H. Potter letter.

10/11/88
Jdo.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE