

RECEIVED  
DEC 22 1987  
ARMS SERVICE



Remington Arms Co

Opt. Cam.

Subject: 308 WIN, S&W 12103  
model 686

V

I purchased the above gun about ten (10) years ago  
& the first week I was out the gun discharged when I  
released the safety. I was slow a bit then the next 2 yrs  
can't remember the first time I broke the down stop.

Right after that you sent me a notice that the  
gun was defective which I would love to take it  
to an appointed place for repair. This so did & the  
gun has worked wonderful ever since, that is until  
this year. I discovered on Monday Nov 30<sup>th</sup> I missed  
a "mild" round. I was when I released the safety  
the gun discharged on its own. I thought maybe  
it was my fault thinking it became to spool.  
I was in Bailey Area. Now 4<sup>th</sup> it did the same  
thing when I went to unload my gun. I think  
I did so have enough money to point the gun  
away from my fellow hunters & I have more  
money than ever before.