

Art Long

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: GOOD

R #: 023941

OUTSIDE WORK: ALL TRIGGER ADJUSTING

DATE: 11-16-72

SCREWS WITHOUT SEAL.

FROM: CHARLES W. FISHER

FIRED AMMO TYPE: REMINGTON

COLUMBUS, OHIO

& CONDITION: _____

GUN #: 6418265

PROOF: R.E.P.-1 ASSEMBLER 13 INSP.: 9 TEST: 13

CODE: AU=3/71

HEADING: O.K.

GA./CAL.: 17 REM.

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: 20 ROUNDS NO PRIMER PIERCING
AFTER SWAGING FIRING PIN HOLE.

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER STOP AND ENGAGEMENT SCREWS OUT OF ADJUST-
MENT. FIRING PIN HOLE NOT SWAGED. SEAR AND TRIG-
GER CONNECTOR DAMAGED.

COMPLAINT: PIERCES PRIMERS, FIRES CLOSING BOLT.

INCIDENT: FOLLOW DOWN

COMMENTS: PRIMER PIERCING CAUSE! DAMAGE TO THE
CORNERS OF THE SEAR AND TRIGGER CONNECTOR,
RESULTING IN FOLLOW DOWN.