

RECEIVING AND ESTIMATING REPORT

COMMENTS
ATT DICK ST JOHN/L REAR SIGHT

INITIAL "R"	CUSTOMER ORDER NO. 1338					89-0225
DATE RECEIVED 01/09/89	DATE OPENED 01/18/89	DATE CODE CA 4-80	SERIAL NUMBER B6203109	MODEL AND GRADE 700 300 BDL/MAG	ORDER R 89-022	
ACCESSORIES W/STUDS		SCOPE BASE				

FROM: WILLIAMSON-PATE GUNSMITH SERVI
DBA/GUNCRAFT, INC (PRO
117 W PIPELINE ROAD
HURST, TEXAS 000076053

SHIP TO: WILLIAMSON-PATE GUNSMITH SER
DBA/GUNCRAFT, INC (PRO
117 W PIPELINE ROAD
HURST, TEXAS 000076053

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059001	WRITE <input type="checkbox"/>	SHIP DATE	ESTIMATE 1/1/89	FEX 15096 UPS
----------------	------------------------------	--------------------------------	-----------	--------------------	------------------

Ship - D.C. FLETCHER
Box 680
VAN ALSTINE, TX

DEAR CUSTOMER:
WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *Finger Problem*

MAIN FAULT: *Finger Assem. out of adjustment*

#33385

PARTS: *Fit Stock Assembly*

*RE-adjust Finger Assem. to function
SPEC. Rifle metal parts
liberated, return
Work done*

REPAIRMAN <i>DKP</i>	PROOF	CLEAN <input checked="" type="checkbox"/>	TEST <input checked="" type="checkbox"/>	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE